

Replacement Parts for TurnControl Rough-In

Replacement Parts for 151.450.00.1 and 151.460.00.1

Item No.	Model No.	Description	List Price
1.1	241.632.00.1	Brass Tee Assembly	\$53.00
1.2	241.766.00.1	Chicago Code Brass Tee Assembly	53.00
2	241.615.00.1	Gasket for drain	10.00
3	241.768.00.1	Stainless Steel Strainer	8.00
4.1	865.066.22.1	Drain Screw for Tub Wall Thickness up to 5/16"	10.00
4.2	241.613.22.1	Drain Screw for Tub Wall Thickness up to 1/2"	22.00
4.3	241.614.22.1	Drain Screw for Tub Wall Thickness up to 3/4"	22.00

Item No.	Model No.	Description	List Price
5.1	241.617.00.1	Overflow Nut for Tub Wall up to 5/16"	\$10.00
5.2	241.621.00.1	Ext. Overflow Nut for Tub Wall up to 3/4"	22.00
6	241.616.00.1	Overflow Flange	15.00
7	242.406.00.1	Gasket tapered for overflow	5.00

Note: For a complete list of available TurnControl Trim, Finishes, Model Numbers and Pricing, refer to Repair Parts Drawings, Euro and Traditional TurnControl Trim sheet.

